











Ver.1




Ver.2








No				PCS	
1	2288	504	16	1	3/8
2	2288	504	16	1	3/8
3	2360	488	16	1	1/8
4	2360	488	16	1	1/8
5	2193	485	16	2	3/8
6	776	476	16	9	4/8
7	2390	555	3	4	1/8
8	2360	60	16	2	2/8
9	804	1116	16	1	6/8
9	804	1116	16	1	7/8
9	804	1116	16	1	8/8
10	804	558	16	1	6/8
10	804	558	16	1	7/8
10	804	558	16	1	8/8
11	804	558	16	1	6/8
11	804	558	16	1	7/8
11	804	558	16	1	8/8
NV01	2358			1	2/8
NN01	2354			1	2/8
SH01	770			2	2/8
RP03	2232			2	5/8
RP01	2232			4	5/8
CH01	2500		12	2	2/8
CH01	2500		6	2	2/8
PS01	774			5	2/8







2/8





No				PCS	
1	2288	504	16	1	3/8
2	2288	504	16	1	3/8
3	2360	488	16	1	1/8
4	2360	488	16	1	1/8
5	2193	485	16	2	3/8
6	776	476	16	9	4/8
7	2390	555	3	4	1/8
8	2360	60	16	2	2/8
9	804	558	16	3	6/8
9	804	558	16	3	7/8
9	804	558	16	3	8/8
10	804	558	16	1	6/8
10	804	558	16	1	7/8
10	804	558	16	1	8/8
NV01	2358			1	2/8
NN01	2354			1	2/8
SH01	770			2	2/8
RP03	2232			2	5/8
RP01	2232			4	5/8
CH01	2500		12	2	2/8
CH01	2500		6	2	2/8
PS01	774			5	2/8





 16x T01	 36x T02	 8x E01	 16x D15	 28x S01	 132x S02	 36x M02
 36x F15	 2x O01	 4x B01	 120x N01	 1x K4	 24x W-30	 9x C01
 4x Z01	 8x Z04	 16x Z02	 8x S06	 5x N02	 5x N03	 1x K6
				 8x V1	 8x P05	
				 8x V2	 8x P05	



Hettich

 2x FR20	 2x FR21	 1x FR22	 1x FR23	 2x FR24	 4x FR25	 6x FR26
 2x FR27	 2x FR28	 2x FR29	 14x FR32	 24x FR33	 36x FR34	 1x FR37
 2x FR38	 1x FR39					

Hettich







 2x FD21	 2x FD22	 2x FD23
--------------------	--------------------	--------------------

 1x NV01	 1x NN01	 2x SH01	 2x RP03	 4x RP01	 2x CH01	 8x PS01
--------------------	--------------------	--------------------	--------------------	--------------------	--------------------	--------------------



1

6x34 8x T01	6x12 8x T02	8x12 8x M02	3,5x30 4x S06	3,5x16 8x S01	V1 4x P05	V2 4x P05
-------------------	-------------------	-------------------	---------------------	---------------------	-----------------	-----------------



2

6x12



14x

T02

8x30




4x

W-30

8x12




14x

M02**x2****3**



Ø15





36x

F15



4





5





6





7



8



9



x9

10

1,6x25

90x

N01

2x25

5x


N02

5x

N03






L=772





8x

PS01



D1=D2



11**12**

3,5x16



8x

S01





4x

**B01**

L=770












2x

SH01

13

 76x32	 3,5x16	 ø4mm	 6 mm	 ø 8mm
2x O01	4x S01	4x Z01	1x K6	8x Z04



14

Hettich

3,5x25



14x

FR32

3,5x16



22x

FR33

2x

**FR28**


2x

**FR29**

2x

**FR27**

L=2358










1x

NV01

L=2354










1x




NN01

15

Hettich



16






17


L=2500



1x CH01




18



1x

FR20



1x

FR21



2x

FR25



2x


FR26

6,3x12,5




12x


FR34






1



2



3



19


3,5x12




32x

S02


2x

SP01

L=2232



2x


RP01**20**

L=2500




12 MM


2x

CH01

21



1x FR22



1x FR23



2x FR24




2x FR26

6,3x12,5



12x FR34




1x FR37



M4x6




2x FR38




1




FR23




FR37





2



3



4



22


3,5x12




32x

S02

x

SP01


L=2232




1x

RP03

L=2232



1x


RP01**23**


L=2500




6 MM

1x

CH01

24

1x

FR20

1x

FR21

2x

FR25







2x

FR26

6,3x12,5





12x

FR34**1****2****3**

25

Hettich

				
2x FD21	2x FD22	2x FD23	24x FR33	1x FR39




26



3,5x12

	
36x S02	3x SP01

L=2232



L=2232






27

L=2500



1x CH01




28



1x

FR20



1x

FR21



2x

FR25



2x


FR26

6,3x12,5




12x


FR34






1



2



3



29


3,5x12




36x

S02


3x

SP01

L=2232




2x

RP01**30**


L=2500




2x

CH01

31



1x FR22



1x FR23



2x FR24




2x FR26

6,3x12,5



12x FR34




1x FR37



M4x6




2x FR38




1




FR23




FR37





2



3



4



32


3,5x12




36x

S02



3x

SP01

L=2232

1x **RP03**


L=2232


1x **RP01****33**

L=2500




6 mm

1x **CH01**

34

1x

FR20

1x

FR21

2x

FR25







2x



FR26

6,3x12,5




12x












FR34**1****2****3**





Ver.1




Ver.2








No				PCS	
1	2288	504	16	1	3/8
2	2288	504	16	1	3/8
3	2360	488	16	1	1/8
4	2360	488	16	1	1/8
5	2193	485	16	2	3/8
6	776	476	16	9	4/8
7	2390	555	3	4	1/8
8	2360	60	16	2	2/8
9	804	1116	16	1	6/8
9	804	1116	16	1	7/8
9	804	1116	16	1	8/8
10	804	558	16	1	6/8
10	804	558	16	1	7/8
10	804	558	16	1	8/8
11	804	558	16	1	6/8
11	804	558	16	1	7/8
11	804	558	16	1	8/8
NV01	2358			1	2/8
NN01	2354			1	2/8
SH01	770			2	2/8
RP03	2232			2	5/8
RP01	2232			4	5/8
CH01	2500		12	2	2/8
CH01	2500		6	2	2/8
PS01	774			5	2/8




2/8








No				PCS	
1	2288	504	16	1	3/8
2	2288	504	16	1	3/8
3	2360	488	16	1	1/8
4	2360	488	16	1	1/8
5	2193	485	16	2	3/8
6	776	476	16	9	4/8
7	2390	555	3	4	1/8
8	2360	60	16	2	2/8
9	804	558	16	3	6/8
9	804	558	16	3	7/8
9	804	558	16	3	8/8
10	804	558	16	1	6/8
10	804	558	16	1	7/8
10	804	558	16	1	8/8
NV01	2358			1	2/8
NN01	2354			1	2/8
SH01	770			2	2/8
RP03	2232			2	5/8
RP01	2232			4	5/8
CH01	2500		12	2	2/8
CH01	2500		6	2	2/8
PS01	774			5	2/8



2/8





 16x T01	 36x T02	 8x E01	 16x D15	 28x S01	 132x S02	 36x M02
 36x F15	 2x O01	 4x B01	 120x N01	 1x K4	 24x W-30	 9x C01
 4x Z01	 8x Z04	 16x Z02	 8x S06	 5x N02	 5x N03	 8x V1
					 8x P05	 1x K6
					 8x V2	


Hettich

 2x FR20	 2x FR21	 1x FR22	 1x FR23	 2x FR24	 4x FR25	 6x FR26
 2x FR27	 2x FR28	 2x FR29	 14x FR32	 24x FR33	 36x FR34	 1x FR37
 2x FR38	 1x FR39					


Hettich

 2x FD21	 2x FD22	 2x FD23
--------------------	--------------------	--------------------

 1x NV01	 1x NN01	 2x SH01	 2x RP03	 4x RP01	 2x CH01	 8x PS01
--------------------	--------------------	--------------------	--------------------	--------------------	--------------------	--------------------








0 1 2 3 4 5 6 7 8 9 10




1

6x34 8x T01	6x12 8x T02	8x12 8x M02	3,5x30 4x S06	3,5x16 8x S01	V1 4x P05	V2 4x P05
-------------------	-------------------	-------------------	---------------------	---------------------	-----------------	-----------------

**1****2****3**

P05



2

6x12



14x

T02

8x30




4x

W-30

8x12





14x

M02**x2****3**

Ø15



36x

F15





7

Ø 15



2x

D15



8

Ø 15



12x




D15

Ø 15mm




12x

Z02



9



10

1,6x25

90x

N01

2x25

5x


N02

5x

N03







L=772





8x

PS01



D1=D2



11

3,5x16




8x

S01





4x

B01



L=770












2x

SH01

12

 76x32	 3,5x16	 ø4mm	 6 mm	 ø 8mm
2x O01	4x S01	4x Z01	1x K6	8x Z04



13

Hettich

3,5x25



14x

FR32

3,5x16



22x

FR33

2x

**FR28**


2x

**FR29**

2x

**FR27**

L=2358










1x

NV01


L=2354




1x

NN01



14


Hettich				
				
2x FD21	2x FD22	2x FD23	24x FR33	1x FR39



15

	
32x S02	2x SP01

L=2232	
1x RP03	
L=2232	
1x RP01	






16


L=2500



1x CH01




17



1x

FR20



1x

FR21



2x

FR25



2x


FR26

6,3x12,5




12x


FR34






1



2



3



18


3,5x12




32x

S02


2x

SP01

L=2232



2x


RP01**19**

L=2500




12 MM

2x


CH01

20



1x

FR22



1x

FR23



2x

FR24



2x


FR26

6,3x12,5



12x

FR34



1x


FR37

M4x6





2x


FR38




1



FR23




FR37




2


FR38




3






FR24



4



CLICK!



21


3,5x12




32x

S02

x

SP01


L=2232




1x

RP03

L=2232



1x


RP01**22**


L=2500




6 mm

1x

CH01

23

1x

FR20

1x

FR21

2x

FR25







2x

FR26

6,3x12,5





12x

FR34**1****2****3**

24

Hettich

				
2x FD21	2x FD22	2x FD23	24x FR33	1x FR39



25

3,5x12

36x

S02


3x

SP01

L=2232

1x **RP03**

L=2232




1x **RP01**

26


L=2500



1x CH01




27



1x

FR20



1x

FR21



2x

FR25



2x






FR26

6,3x12,5



12x

FR34



28


3,5x12




36x

S02


3x

SP01

L=2232




2x

RP01**29**


L=2500




2x

CH01

30



1x FR22



1x FR23



2x FR24




2x FR26

6,3x12,5



12x FR34




1x FR37



M4x6




2x FR38




1




FR23




FR37





2



3



4



31


3,5x12




36x

S02



3x

SP01

L=2232

1x **RP03**


L=2232


1x **RP01****32**

L=2500




6 mm

1x **CH01**

33

1x

FR20



1x

FR21



2x

FR25



2x


FR26

6,3x12,5




12x


FR34



①



②



③

